

1		TA001	DA001	+	15000	30	20
2	1 2#	TA001	DA002		8500	15	30
3	1# 2#	TA002	DA003	+ +	460000	30	70
4	1# 2#	TA003	DA004		460000	[a] 0.0003	
5	1# 2#	TA023	DA005	SDS SCR +	602000	30	30
6	1 2#	TA004	DA006		42000	15	
7	1 2#	TA005	DA007		42000	15	
8	3 4#	TA006	DA008		300000	15	
9	1 2#	TA007	DA009	+WSA +SCR	30000	100	
10	3 4#	TA008	DA010	+WSA +SCR	30000	150	5
11						100	5

62		TA040	DA038	37000	30
63		TA039	DA037	820000	30
64		TA053	DA050	685000	25
65		TA038	DA036	275000	30
66		TA037	DA035	270000	30
67		TA087	DA082	275000	25
68		TA076	DA069	755000	25
69	A2				

106	1#	TA065	DA062		1600000	20
107	2#	TA067	DA063		222500	50
108	2#	TA068	DA064		1600000	20
109	1#	TA070		LT	222500	50
110	1#	TA170			222500	50
111	2#	TA073		LT	222500	50

136	1#	TA002	DA004	,SDS	,	+	81849	20 SO ₂ 150 NO _x :300
137	1#	TA003	DA005	,SDS	,	+	98000	20 SO ₂ 150 NO _x :300
138	1#	TA004	DA006	,SDS	,	+		

157	2#	TA082	DA076	+	119098	30	30
158	1#	TA006	DA007	+	137900		